	Ty		Hits	Search Text	DBs	Time Stamp	Comments	Error Definition	Errors
1	IS &R		4	((359/290,291,295,298) or (348/750,756,770,771,77 5)).CCLS.	USPAT; US-PGPUB	2003/ 10/17 09:41			0
2	BR S	L 2	1 2 0	1 and and 20030501	USPAT; US-PGPUB	2003/ 10/17 09:42	-		0
3	BR S	L 3	1 0 3		USPAT; US-PGPUB	2003/ 10/17 09:42			0
4	BR S	L 4	4 8		USPAT; US-PGPUB	2003/ 10/17 09:42			0
5	BR S	L 5	1 0 8	3 or 4	USPAT; US-PGPUB	2003/ 10/17 09:42			0
6	BR S	L 6	7		USPAT; US-PGPUB	2003/ 10/17 09:42			0
7	BR S	L 7	4	6 and switch\$3	USPAT; US-PGPUB	2003/ 10/17 09:45			0
8	BR S	L 8	4	7 and (digital with (mirror\$3 or micromirror\$3))	USPAT; US-PGPUB	2003/ 10/17 09:43			0
9	BR S	L 9	3		USPAT; US-PGPUB	2003/ 10/17 09:44			0
10	BR S	L 1 0	6		USPAT; US-PGPUB	2003/ 10/17 09:44			0

	Ту		Hi ts		DBs	Time Stamp	C o m m e n t s	Errors
1		L 1 3		digital\$2 with micromirror\$3	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/ 10/17 09:53		0
2	C	L 1 4	3 5 4 6	DMD	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/ 10/17 09:53		0
3		L 1 5	4 1 3 7	13 or 14	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/ 10/17 09:53		0
4		1	5 8 4	15 and @pd>20030501	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM TDB	2003/ 10/17 09:53		0
5	BR	L 1	3 1 3	16 and (micromirror\$3)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/ 10/17 09:53		0
6	BR S	L 1 8	1	17 and SRAM	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/ 10/17 09:57		0
7	BR S	L 1 9		18 and (second with electrode\$1)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/ 10/17 09:58		0
8	BR S	L 2 1	3	19 and switch\$5	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/ 10/17 09:58		0